

Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Collected b	nager FRANK BEODRAY y: (Print and Sign) T T Smith C WESTON SOLUTIONS, MC. Email	w.S	Project Info			Turn Around Time: Normal	Pressurized by: Date:			
	CityFax	State	Zip		0405.014.00 DECP41 VOC		Rush 2 WEEK specify	Press	surization (
			Date	Time					ssure/Vac	1
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested	Initial	Final	Receipt	Final (psi)
	Ex. 6 P Names, Addresses and 5.5/03708	21010	10/27/08	0913	TO 15		30	8		
	Ex. 6 P Names, Addresses and phon 4 10 3808	34447	10/27/08	0913	TO 15 LL		30	7,5		
Me -	- CAST ITEM -									
	,									
JA 19										
A JC	ed by: (signature) Date/Time /// Date/Time ded by: (signature) Date/Time	FEDE	y: (signature) X /0/s y: (signature)	25/08 10	115	Notes:				W.—————
Tiomiquione	Su Sy. (Signature) Date in the	T 10001V0d D	y. (dignataro)	Datosimo						
Relinquishe	ed by: (signature) Date/Time	Received b	y: (signature)	Date/Time						
Lab	Shipper Name Air Bill #			°C) C	Condition	Custody Se	eals Intact?	Work	Order #	VE.
Use	e					Yes No	None			
Only	1			n tu						



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

	The second secon									
	Manager FRANK BEODRAY			Project Info):		Turn Around Time:		Only urized by:	
	by: (Print and Sign) T J Smith C		uts_	P.O. # 600	63/		Normal	Date:	anzed by.	
Company	WESTON SOLUTIONS. INC. Email _				0405.016,00	2.0173.00	Control of the Contro			
\ddress_	City	State	Zip	Project #	3 - 20: 1/00	A	2 WEEK		urization (
Phone	Fax			Project Name	DECP41 VOC	PEUMI	specify		N ₂ He	е
			Date	Time				7'	ssure/Vac	
Lab I.D	. Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested	Initial	Final	Receipt	Final (psi)
	Ex. 6 P Names, Addresses and 55/02708	21010	10/27/08	0913	TO 15		30	8		
	Ex. 6 P Names, Addresses and p TA 10 2 30 8	34447	10/27/08	0913	TO 15 LL		30	7.5		
1/2 -	CAST ITEM -		-							
										1-2
_			*							
5 1: -:		ID t 11	2-1	Data Circa	T	Notes				
Relinqui	shed by: (signature) Date/Time	FED £	y: (signature)	Date/Time		Notes:				
Relinguis	shed by: (signature) Date/Time			Date/Time						
Relinqui	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time						
Lab	Shipper Name Air Bil	I #	Temp (°C)	Condition	Custody Se	eals Intact?	Work	Order #	
Use						Yes No	None			
Only										



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ____ of ___

Project M	anager trail Beating	2111		Project Info):		Turn A		Pressi	Only urized by:	12.00 19.00
	by: (Print and Sign) King King King	41		P.O. #	\$631		Nor	rmal	Date:		-1
	Wisher Solutions Email Email	State	Zin	Project #	15.46.44).71	.164	Rus	sh	Pressi	urization (as:
	37)571-440L Fax	State	ΖΙΡ	Project Name	, Delphi VUC site	2	Sne	ecify		N ₂ He	
110110		Date	Time					er Pres	sure/Vac	uum	
Lab I.D.	Field Sample I.D. (Location)	Can #	The state of the s	of Collection	Analyses I	Requested		Initial	Final	Receipt	Final (psi)
	EX. 6 P N 55 W6 \$3 48	741-1	6-3-08	1606	TO 15			75	4		
	Ex. 6 P Na IA \$ \$ \$ \$ \$ \$ \$	3729	6-3-08	1424	TO 15	1-1		300	8		
	NIA	35250			None			Same :			
								4			
	thed by: (signature) Date/Time		y: (signature)	Date/Time	0	Notes:	50	not us	ed to	Samo	15
	shed by: (signature) Date/Time		y: (signature)	Date/Time	ī	a party sin	174	dire	coring	ontop.	1
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Lab	Shipper Name Air Bill	Temp (°C) C	Condition	Custody Se	als Inta	ict?	Work	Order #		
Use Only						Yes No	No.	ne		, and	
Office					*						r -



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page _ of _ _

	anager Frank Bodiny		,	Project Info):		Turn Aroun Time:		Ind Lab Use Only Pressurized by:		
	by: (Print and Sign)			P.O. #	60631		□ No		Date:	arized by.	E.
	Email _			Project # 3	P4.65.416-917	3.00	☐ Ru			urization (2001
	City								Press		
Phone <u>(</u>	3)825-7544 Fax (S17)	8	Project Name	Drlph VOC P	lune	sp	ecify		N ₂ He	9	
Lab LD	Field Comple I.D. (Leastion)	Can #	Time of Collection	Analyses	Requested				sure/Vac		
Lab I.D.	Field Sample I.D. (Location)	of Collection	or Conection				Initial	Final	Receipt	Final (psi)	
	JCENER JAI OG 1208	34416	6-12-48	1415	TO 15 L			27.5	5		
	J Center IA 2 1061248	34222	11	1630	11			30	5		
* 1-15+	Item		141								*
111, 11											
47777											
			1								14.4
A TIT			4								
			+ 7								
			*								-0-1
Relinquis	hed by: (signature) Date/Time	Received b	y: (signature)	Date/Time	T	Notes:					
7	111 6-13-29/1745		*	404)46							
Relinquis	hed by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Relinquis	hed by: (signature) Date/Time	Date/Time	3								
Lab	Shipper Name Air Bill	Temp (°C)	Condition	Custody Se	eals Int	act?	Work	Order #		
Use					Yes No) No	ne				
Only											



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page _____ of _____

	Jected by: (Print and Sign) Fondy XI Hand + Tim Smith All 11				:		Turn A Tin		Lab Use Pressi	Only urized by:	
	y: (Print and Sign) Kindy Kinding I In Son Washn Solutions Email		- Jacob	P.O. #			☐ Nor	mal	Date:		
	City		Zip	1	\$5. \$12. \$\$3.		Rus 3 d		Pressi	urization (Gas:
Phone (93)531-4490 Fax (937)	531-44øl		Project Name	Delphi voc	Plume RV	spe			N ₂ He	е
Lab I.D.	Field Sample I.D. (Location)	Can #	Date of Collection	Time of Collection	Analys	es Requested		Canis	ter Pres	sure/Vac	
	SV17-672508	1562	7-25-08	1029	TOK	5		J8:[3	5.16		(psi)
	5v18- Ø725Ø8	34484	7-25-08		TO			29.77	-		
	Sv 19-072568	4165	7-25-48		TO 1	5		2959	17.36		
* Last	Hem									_ *	
74	ed by: (signature) Date/Time 7-25-07 230 ed by: (signature) Date/Time		by: (signature)	Date/Time		Notes: SVIB-07250				ent, ple	-04
Relinquished by: (signature) Date/Time Received by: (signat			oy: (signature)	Date/Time		5v19-8725					final
Lab Shipper Name Air Bill # Temp (*) Use Only			(°C) Condition Custody Seals Inta				_				



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

	anager Fronk Brodies	-//	Mint	Project Info		Turn Around Time:	nd Lab Use Only Pressurized by:		7
	by: (Print and Sign)	5 5.00	1 des	P.O. #		☐ Normal	Date:		1
	City	State	Zip	7	85. ph. 603. 6316.602	☐ Rush		rization (
Phone 73	7)531-4471 Fax (737)5	31-4401		Project Name	Delphi VOC Plumo KV	specify		N₂ H∈	
Lab I.D.	Field Sample I.D. (Location)	Can #	Date of Collection	Time of Collection	Analyses Requested	Canist	er Pres	Receipt	Final (psi)
74.0	SV17672508	1567	7-25-08	1029	TO 15	28:13	5.16		
	SV18- 072568	34484	7-25-48	1056	TO 15	29.77	9		
71.8	Sv 17- 473548	4165	7-25-98	1194	TO 15	29.59	17.36		
* ! = ,+	III M							- *	
	P							N.	
									1721
i X	e magazi								
Relinquis	hed by: (signature) Date/Time	Received b	y: (signature)	Date/Time	Notes:	cy relladed to	a mela	-it; pl-	-15.₹
Relinquis	hed by: (signature) Date/Time	Received b	y: (signature)	Date/Time		1 analysis		, i	
Relinquis	hed by: (signature) Date/Time	Beceived b	y: (signature)	Date/Time		es sollested			tiral
Tiemiquis	Tiod by (digitaliars) Date, time	110001100	y. (olgilalaro)	d d	Amount by	are bioreal	ud and	452	
Lab	Shipper Name Air Bill	Temp (°C) C	ondition Custody Se	als Intact?	Work (Order #		
Use			1 1 1		Yes No	None			
Only									



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

	1 . 1
Page	of

	lanager	1 : 10 . 1		Project Info):		Turn Around Time:	Ad Lab Use Only Pressurized by:			
	by: (Print and Sign)	1		P.O. #			☐ Normal		mzod by.	4.00	
Address_	CityFax		Zip		MUST ON STATE		Rush	Pressi	urization G N_2 He		
1 -			Date	Time			Canis	ter Pres	ssure/Vac	uum	
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested	Initial	Final	Receipt	Final (psi)	
	APA-08-35.3		restrict to	1000	ply To	15	26.0	25			
	EPA-18- IA >		H-M-	Hw. A.	My 70	15 44	211	71			
										. I ×	
					*						
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time			الم والحراء ا			T.	
Relinquis	shed by: (signature) Date/Time	Received b	y: (si <mark>gnature</mark>)	Date/Time			1 - 11-		TEAN		
Relinquis	shed by: (signature) Date/Time	y: (signature)	Date/Time		i Se True h	o ronly, ly			11347		
Lab	Shipper Name Air Bill	Temp (°	C) C	ondition	Custody Se	als Intact?	Work	Order #			
Use						Yes No	None				
Only											



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page of ___

	anager		Project Info	:		Turn Around Time:		Lab Use C	only Irized by:		
	by: (Print and Sign) Email _			P.O. #	631		☑ No	rmal	Date:		
	City			Project # 🍱	us-b(C + 2, 10	05.44	☐ Ru	sh	Pressu	rization G	as:
	53 \439-3337 Fax (5))		Project Name	endon ve P	Line	sp	ecify		N ₂ He	,	
			Date	Time				Canis	ter Pres	sure/Vac	uum
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	s Requested		Initial	Final	Receipt	Final (psi)
	3.5 m. Apr. 56.1 (2013.20) 1/8	3764	4-29-48	1700-	TO 15			29	Ø		
	71- to 55 10092508	36.433	41-14-14	1738	TOB			37	4		
/+								-			-*
					-			The same			
										Page 1	
											C 18
				-							
70	thed by: (signature) Date/Time		by: (signature) by: (signature)	Date/Time Date/Time		Notes:					
						Darlyhan					
Relinquished by: (signature) Date/Time Received by: (signature				Date/Time							BIN
Lab	Shipper Name Air Bil	Temp (c	(C)	Condition	Custody Se			Work	Order #		
Use Only						Yes No	No	ne			
Ciny											

ACC	E	5	No.

CHAIN OF CUSTODY

FED-EX Tracking # Bottle Order Control # //257 2 PAGE _ OF _____
Lab Quote # Lab Job #

Air Sampling Field Data Sheet					15	
Client / Reporting Information			Weather Pa	irameters	Requeste	d Analysis
Company Name WESTON SOLUTIONS	Project Name: Dolphi Voc Plum	e Site	Temperature (Fahrenheit) Start:	Maximum		
2566 Rohnle Dr.	Street		Stop	Minimum		
City MIamisburg State 2ip 45342 Project Contact E-mail Kandy Kirkland / Cisa Graczyk Phone # 937-384-4248 /312-424-3339 937-384-4201/312-424-3330	City Dayton	State				
Project Contact	Project#	Un	Atmoshpheric Pressure (inches Start:	s of Hg) Maximum:		
Rundy Kirkland / Cisa Graczyk	Project # 20405, 0/6.002, 0/73, Client Purchase Order #	60		Minimum	g List	
937-384-4248 /312-424-3339 937-384-4201/312-424-3330	Client Purchase Order #		Stop:	Reporting		
Sampler(s) Name(s)			Other weather comment:			
Air Type Sampling Equipn	nent Info Start Samp	ing Information	Stop Sampli	ing Information	ro-15	
Indoor(I) Soil Vap(SV) Canister Size	Flow Time Controller (24hr	Canister Interior Pressure Temp Sampler	Time (24hr	Canister Interior Pressure Temp Sampler	Standard	
Lab Sample # Field ID / Point of Collection Ambient(A) Serial # 6L or 1L	Serial # Date clock)	("Hg) (F) Init.	Date clock)	("Hg) (F) Init.	S	_
EPA-0Z-IA I A641 6L	FC284 6-6-07 0920	30" 70 DZ	6-7-07 1010	6" 70 D	V	
EPA-03-SS 5V A707 6L	FC227 6-6-07 1025	29" 70 D	16-7-07 1140	6" 10 F	~	
EPA-04-SS SV A245 6L	PLOSO 6-6-07 1100	28" 70 D	6-7-07 1125	5" 70 DZ	1	
EPA-05-SS SV 4377 6L	FCZ81 6-6-07 1140	30" 70 D	16-7-07 1200	9" 70 D		
		26" 70 0=	6-7-07 1215	511 70 0		
						_
					\vdash	-
Towns of Time (Paris and April	Data Delive	rable Information		Comments / Remarks		1
Turnaround Time (Business days) Standard - 15 Days 10 Day 5 Day 3 Day 2 Day 1 Day Other	All NJDEP TO-15 is ma Comm A Comm B Reduced T2 Full T1 Other:		*Please provide	results in formats. h levels of TCE, TCA, DCE and	PD= 0 PCE 1 Tolus	ene
Sample Custody must be do	cumented below each time samples char					
Refinguished by Laboratory 1 Local Linguished by: Date Time: Received By: Received By: Received By:	Relinquished 2	rele	Date Time:	Received By: 2		
Relinquished by: Date Time: Received By: 3	Relinquished 4	ву:	Date Time:	Received By:		
Relinquished by: Date Time: Received By: 5	Custody Seal	I intact on receip	+ ; #202 applie	d on outbound s	hypmi	mt



CHAIN OF CUSTODY

Lab t	pratories	Air	Sampiir	ng Fleia	Data Sne	3et												D	-1-d A-	-timetal
		4		Client / Re	eporting Infor	mation					V-				arameters			Reques	sted An	alysis
Company Name							Project Name						Temperature (Fal	renheit)				1		
Weston So	olutions, Inc						Delphi VOC	Plume					Start:		Maximum:		- 1	1 1		
Address							Street													
2566 Kohn	ile Dr						S. Ardmore	St.			21.4		Stop		Minimum:			1	- 1	
City				Zip			City				State		The second second second	TAKE T	31 549000			1 1		
Dayton			ОН	45342			Dayton				OH		Atmoshpheric Pro	essure (inche	Maximum:			i 1		
Project Contact			E-mail	- 72	7.		Project # 20405.016.002	0172.00					Start:		Maximum.			List		
Randy Kirl	kland		randy.kirklai	nd@weston	solutions.con	1	Client Purcha						Stop:		Minimum:			g		
937-384-42	200		937-384-42	01			Chefft Purcha	ise Order #					Stop.		Will lift lutti.			늍	. 1	
Sampler(s) Name(s)	200		337-304-42	U I									Other weather co	mment:				Reporting		
campion(s) manuals)													Culei Weather Co	amment.				1 K		
				Air Type	Sampling	Equipn	ment Info Start Sampling Information					Stop Samp	ling Inform	ation		0-15				
1			1										100					1		
				Indoor(I)		Capiatas	Flow		Time	Canister	Interior			Time	Canister	Interior		Standard	. 4	
	sales le terrerais o	1_ 22		Soil Vap(SV)	Canister	Canister Size	Controller		(24hr	Pressure	Temp	Sampler		(24hr	Pressure	Temp	Sampler	ᇣ		
Lab Sample #	Field ID /	Point of Co	ollection	Ambient(A)	Serial #	6L or 1L	Serial #	Date	clock)	("Hg)	(F)	Init.	Date	clock)	("Hg)	(F)	Init.	S.	_	
	F	PA-03-IA		1 1	A775	6L	FC126	7/19/07	0930	30	68	RK	7/20/2007	0930	8	68	DR	X		
					71170	- OL	1 0 120	7710701	0000	- 00	- 00	IXIX	1120/2001	0930	0	- 00	DIX		-+	_
	E	PA-04-IA		I	A322	6L	FC171	7/19/07	0940	30	72	RK	7/20/2007	0940	6	72	DR	X		
	ED4	04 14 0111						6	DV1000 4000									V		
EPA-04-IA-DUP		,		A645	6L	FC174	7/19/07	0940	30	72	RK	7/20/2007	0940	7	72	DR	X			
EPA-07-IA			A184	6L	FC241	7/19/07	0920	30	73	RK	7/20/2007	0920	6	73	DR	X				
		AUTIA		•	7,104	- OL	10241	1119/01	0920	30	73	IXIX	1120/2001	0920	-	13	DK		-	
	E	PA-10-IA			A135	6L	FC317 7/19/07 1005			30 65 RK			######### 1005 5			65	DR	X		
													1							
				7																
						_					_				-				-	-
													£							
													4			l			A 9	
	Tur	naround Time (Business day	(2)					Data Delive	rable inform	ation				Comments	Pamark				
Standard - 15		The raine (Dusiness days	-1				All NJDEP T	COMPANY PROPERTY.	5 1 (9 (E) - 1 (B ()) (1 () (B ())			Possible high	levels of				roform		
	10 Day			Approved By:				Comm A	0-10 13 1110	1			l ossible riigi	i ieveis oi	ICL, FCL,	JOE, TO	A, & CHIO	Ololin		
	5 Day	x					. ,	Comm B		1										
	3 Day		1					Reduced T2		1			Please provi	de results i	n odf and e	dd forma	at			
	2 Day		1	Date:				Full T1		1			I i lodgo provi	ao roodno r	ii pai ana o	20 1011110				
8	1 Day						22	Other:	See Quote											
	Other						(1)													
				Samp	le Custody mi	ust be do	cumented bel	low each time sa	imples char	ige possess	ion, inclu	ding cour	ier delivery.					9025		
Relinquished by Laborator	ry:		Date Time:		Received By:				Relinquished	By///,	/		Date Time:	1	Received By:					
1					1				2	110	9		7-24-57	1730	2					
Relinquished by:			Date Time:		Received By:				Relinquished	By:			Date Time:		Received By:					
3					3		4 C				4									
Relinquished by:			Date Time:		Received By:		Custody Seal #													
5	5							1												



CHAIN OF CUSTODY

FED-EX Tracking #	Bottle Order Control #	PAGE_1_ OF _1_
Lab Quote #	Lab Job#	

L d D d	oratories	AII	Sampin	ig Fleid	Data Sne	eet														
			Date Asset	Client / Re	eporting Infor	mation		D (8/2 f/s)	WEDTER	PESSION.		W TOO MI	Remote to the	Weather F	arameters			Reques	sted An	alysis
Company Name							Project Name	9:					Temperature (Fa	ahrenhelt)						
Weston So	lutions, Inc						Delphi VOC	Plume					Start:		Maximum:			1 1	- 1	
Address							Street	/4											- 1	
2566 Kohn	le Dr						S. Ardmore	St.					Stop		Minimum:			1		. 1
City			State	Zip			City				State							1 1	- 1	
Dayton			ОН	45342			Dayton	Dayton OH					Atmoshpheric Pressure (inches of Hg)						- 1	
Project Contact			E-mail				Project #						Start:		Maximum:			ایدا	: 1	
Randy Kirl	kland		randy kirklar	nd@weston:	solutions.com	n D	20405.016.00	2.0172.00										List		
Phone #	Maria		Fax #	IG(G) IT GOLGIN	ocidacino.com		Client Purch	ase Order#					Stop:		Minimum:			E		
937-384-42	on.		937-384-420	01														ਰ	- 1	
Sampler(s) Name(s)											_		Other weather o	omment:				Reporting		
Dave Robi	nson																	5 1	1	. 1
				Air Type	Sampling	Fauion	nent Info	9	Start Samp	ing Inform	ation		0	Stop Samp	ling Inform	ation		TO-15		
						,qp	T						8	T : - :	T					a 1
			- 1				Flour	4	Time	Canister	Interior		10	Time	Canister	Interior	1 1	Standard		
			- 1	Indoor(i)	Conintor	Canister	Flow		(24hr	Pressure		Sampler	10	(24hr	Pressure			2		
Lab Sample #	Field ID /	Point of Co	lection	Soil Vap(SV) Ambient(A)	Canister Serial #	Size 6L or 1L	Serial #	Date	clock)	("Hg)	(F)	Init.	Date	clock)	("Hg)	(F)	Init.	Sta		
Lab Gampie #	TIEIG ID 7	1 Ollit Or OC	Mection	Ambient(A)	Genal #	OL OF TE	Ochai #	Date	CIOCIN	(rig)	1.7	III.C	20.0	0.00.07	1	1				-
	E	PA-08-IA	- 1		A479	6L	FC294	8/2/07	11/15/03	1/30/00	74	DR	8/3/2007	0:00	3	74	DR	X		
		A COURSE AND ADDRESS OF						100					iii .							7 - 1
								2)												
								1					8							
													跳							
																			,	
								8					N .					-		
										5										
								JA					W.					\vdash		_
								6					100) I
														1		-	_	\vdash	-	
													8	9		1				
												_		-	_	_	\vdash	\vdash	=	-
1				()				40					#		1	1		1 1		
						-	-	10	_			_		+	+	_	_	\vdash		
													8		1					
						+	1	10					-	-	-	1				
				(!				15					1							
	Turr	naround Time (Business days	s)		7. S-118			Data Delive	rable Inform	ation	200	West of the second	-	Comments					TEXT !
Standard - 1	5 Davs							All NJDEP T	O-15 is ma	ndatory Ful	IIT1		Possible hi	gh levels of	TCE, PCE,	DCE, TO	A, & Chlo	roform		
	10 Day			Approved By:				Comm A					2							
	5 Day	X			-		- 8	Comm B		1										
	3 Day							Reduced T2		1			Please pro	vide results	in pdf and e	dd forma	at.			
	2 Day			Date:				Full T1		1			2							
	1 Day			,	-			Other:	See Quote				6							
	Other		Ì					130												
SAVIJIV N NOS		S. 1804	C-1200	Samp	le Custody m	ust be do	cumented be	low each time s	amples char	ge possess	ion, incl	uding cour	ier delivery.		20 80 773		THE PERSON	-17.50	CHEST.	A
Relipquisting by Laborato	1 //		Date Times		Received By:			-	Relinquished				Date Time:		Received By					
		4	Date Timey	15:30	1				2	•					2					
Belinquished by:			Date Time:		Received By:				Relinquished	Bv:			Date Time:		Received By					
3			Sard Hille. (3				A			4								
	3 Professional Pro-			Custody Seal #					<u> </u>					Ē						
reinquisnea by:	nquished by: Date Time: Received By:		Custogy Seal #																	



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ____ of ___

Project Manager				Project Info:			Turn Around Time:		Lab Use Only Pressurized by:		
	by: (Print and Sign)		96	P.O. #			Norma			rizea by.	- E - I
	Email City		Zin	Project #			Rush		-	rization G	
	1916- 2016 Fax			Project Name Dolph. Luc Plane			specify		N ₂ He		
Lagran			Date	Time			Canis		er Pres	sure/Vac	uum
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested	In	itial	Final	Receipt	Final (psl)
-,15:											
-1, 1	The second secon									-A-P-01	Proces
. Vite											
3											
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time	9	Notes:	± 55	S4 12	which	ido ,	no [±]
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time		andyse,					
					ė.	w # 3435	7 inca	N/B	10"4	y mother	1.
Relinquis	shed by: (signature) Date/Time	y: (signature)	Date/Time			place a real account					
Lab	Shipper Name Air Bill #		Temp (°	C) C	ondition	Custody Sea	als Intact?		Work C	order#	
Use						Yes No	None				HILL!
Only											



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page of

	oject Manager Kandy Kirkland				Project Info:				Lab Use Only Pressurized by:			
Collected I	by: (Print and Sign)	david. Co	binson utionsicim	P.O. #			☐ Normal		Date:			
	MESTON Solutions Email &		Zip 45402	Project # 2.0405.016.002.0173.00 Project Name Dolphi VOC				sh	Pressi	urization G	Gas:	
	37-572-3630 Fax 937-	531-44		Project Name Dolahi VOC				ecify	N ₂ He			
Date				Time			Spo			sure/Vac		
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection		Analyses	Requested		Initial	Final	Receipt	Final (psi)	
0	EPA-08-TA3	33974	3-27-08	10:05	TO15 LL	THO		30"	8"	2		
- 47	EPA-08-553	4247	3-27-08	-	TO15			30"	4"			
e julianje			1 /								1 9	
A										4-11-1		
			-		la participation of the second							
					1							
	- 7a											
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time		Notes:						
Relinquish	ned by: (signature) Date/Time		y: (signature)	Date/Time								
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time								
Lab	Shipper Name Air Bil	l #	Temp (°C) C	Condition	Custody Se	als Inta	ict?	Work (Order #		
Use Only						Yes No	No	ne				
Only												



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ___ of ____

-	roject Manager Fronk Beodray			Project Info:				Turn Around Time:		Lab Use Only Pressurized by:		
	y: (Print and Sign) Randy Kirlland Weston Solutions Email	The		P.O. #(.063/		Nor 🕰		Date:	u. 1200 by		
	City		Zip	Project # 20	405.016.002.017	3.04	Rus Rus	sh	Pressurizati		Gas:	
	37)531-4480 Fax(937			Project Name	Delphi va Si	te	specify		N ₂ He			
			Date	Time				Canis	ter Pres	ssure/Vac	uum	
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses Re	equested		Initial	Final	Receipt	Final (psi)	
	J CenterSS1880708	5606	8-7-08		TO 15			30	9			
	J Center SS2 Ø80708	31154			TO 5			Зø	12			
	J center IA1 080708	5636			TO 15 LL			3ø	198			
	JCenter IA2080708	4189	<u> </u>		TO 15 LL			30	7			
* Last	Item										*	
Relinquish	ed by: (signature) Date/Time	Received b	by: (signature)	Date/Time	N	otes:						
	ed by: (signature) Date/Time		, ,	Date/Time								
Relinquisne	ed by: (signature) Date/Time	Received	y: (signature)	Date/Time								
Lab	Shipper Name Air E	Bill #	Temp (°C) C	Condition C	Sustody Se	als Inta	ct?	Work	Order #		
Use Only						Yes No) Nor	ne				



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page _ /_ of _ /_

	roject Manager Find Broker			Project Info		Turn Arou Time:		Lab Use Only Pressurized by:		
Collected I	by: (Print and Sign) Foody Killard	74/6		PO# /	01631		Normal			
Company_	Wrston Solutions Email							Date:		
Address	City	State	Zip	Project # <u>→</u>	Rush	Press	surization (Gas:		
Phone	137)531-4484 Fax(937)	Project Name Delph VIC Lite			specify		N ₂ He			
			Date	Time			Ca	nister Pre	ssure/Vac	uum
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested	Initi	al Final	Receipt	Final (psi)
	J Carter SSIGROTUS	5606	8-7-48		TO 15		3	ø 9		
	J Carter 552 480708	31154			TO 15		34	12		
14	J Ce, de, TAI 234748	5636			TO 15 L		34	19		
	JC-Mer IAZ W80708	4189			TO 15 44		30	5 7		
* Lost	It-in									
										1121
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time		Notes:				
	E-8-48/1714									
Relinquist	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time						
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time						
Lab	Shipper Name Air Bill	#	Temp (°C) C	Condition	Custody Sea	als Intact?	Work	Order #	
Use						Yes No	None			
Only										



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

	roject Manager FRANK BEODRAY				Project Info:				Lab Use Only Pressurized by:		
Collected	by: (Print and Sign) T- Smith 4	douts	8	P.O. # (40	431		Time: Normal		urizea by.		
Company	ME STON Email _						Date:		-24		
Address _	714 E MONUMENT City DAYTON	State 2/1_	Zip 45404	Project # 20405,016 - 003 - 0178.0			Rush 14-DAY	Pressurization Gas:			
Phone 9	37 531 4400 Fax 937	531 44	01	Project Name DELPHI VOC PLUME			specify N ₂			Э	
			Date	Time			Canis	ter Pres	sure/Vac	uum	
Lab I.D.	Field Sample I.D. (Location)	Can #		of Collection	Analyses	Requested	Initial	Final	Receipt	Final (psi)	
	Ex. 6 P Names, Address 55091808	33542	9/18/08	1135	70 15		30	7			
	Ex. 6 P Names, Addresses and p A 091808	34024	9/18/68	1135	70 1512		39.5	5			
711-	- LAST ITEM										
									TE A		
			74-						20		
1											
	shed by: (signature) Date/Time			Date/Time	~	Notes:					
- //	July 9/19/08 15/0	FEOR		9/08 15	80						
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Relinquis	shed by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Lab	Shipper Name Air Bill	#	Temp (°C) C	Condition	Custody Se	als Intact?	Work	Order #		
Use						Yes No	None				
Only											



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ____ of ____

Project Ma	inager Frank Besdray	Project Info):	Turn Around Time:		Lab Use Only Pressurized by:					
Collected b	by: (Print and Sign) Randy Kickland			P.O. #(2063/		∑ No	rmal	Date:		
	Wester Solutions Email _			Project # 🛶		Rush		Pressurization Gas:			
32	City 7) («፲- 3¢۶າFax			Project Name Pelphi Voc Plume			specify		N ₂ He		
Priorie 13	1)641-3481 rax	CONTRACT OF A	201				Spe	-	er Pres	sure/Vac	
Lab I.D.	Field Sample I.D. (Location)	Can #	Date of Collection	Time of Collection	Analyses	Requested		Initial	Final	Receipt	Final
	Jackson Center - 552-040109	34362	4-1-99	1335	TO 15			346	4"		
	Jackson Center- SSI-040/099	915		1310	TO 15			29.4	6"		
	Jackson Center- In1-040109	34382		1320	TO 15	1		29.6	7"		
	Jackson Center-Ind-040/09	14791		1335	TO 15	L		29.6"	75		
* Last	Dem -								*		-¥
	ned by: (signature) Date/Time 4-3-\$9 / 1534	•	y: (signature)	Date/Time		Notes:					
Helinquisa	ed by: (signature) Date/Time	neceived t	ry. (Signature)	Date/Time							
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Lab	Shipper Name Air Bil	#	Temp ((°C) C	Condition	Custody Se	eals Inta	ict?	Work	Order #	
Use Only						Yes No	o No	ne			



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ____ of ____

	roject Manager			Project Info:				Around ne:	Lab Use Only Pressurized by:		
	Print and Sign) Email			P.O. #	9671		□ Normal		Date:		
	City			Project #				sh	Pressurization Gas:		
	71(u)-1481 Fax			Project Name Project Name				ecify	N ₂ He		
			Date	Time						sure/Vac	
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection	of Collection	Analyses	Requested		Initial	Final	Receipt	Final (psi)
	Jeckson Center - 552-0440109	3-1-364	4-1-49	1335	TO 15			Hille	4"		
	Jackson C-Her- 551-2416/99	915		10-14	TO 15			39.6	6"		
	Back Son Carter - Int - WHILE	311332		1300	TO 15 4			35.6			
	July of Cotor . I. 2-440/49	14791	4	1335	NTO 15	1-1-		39.6	7.5		
* Last	Hen -										-4
					- 444	-	5 IV	37	THE STATE OF		
×											
							-				
17.75	Control of the second			7 727		1 100 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	400				
	*				ray Freed	J. web G. 2007				L III	
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time	The same of	Notes:					
	4.1-41/1500										
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Relinquish	ned by: (signature) Date/Time	Received b	y: (signature)	Date/Time							
Lab	Shipper Name Air Bill	#	Temp (°C) C	Condition	Custody Se	als Inta	act?	Work	Order #	
Use						Yes No	No.	ne			
Only											



Sample Transportation Notice

Relinquishing signature on this document indicates that sample is being shipped in compliance with all applicable local, State, Federal, national, and international laws, regulations and ordinances of any kind. Air Toxics Limited assumes no liability with respect to the collection, handling or shipping of these samples. Relinquishing signature also indicates agreement to hold harmless, defend, and indemnify Air Toxics Limited against any claim, demand, or action, of any kind, related to the collection, handling, or shipping of samples. D.O.T. Hotline (800) 467-4922

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA 95630-4719 (916) 985-1000 FAX (916) 985-1020

Page ____ of ___

	nager trank Badany	1 17	,	Project Info);	Turn Around Time:	Lab Use Only Pressurized by:		
	Y: (Print and Sign)			P.O. #	(DC) [☑ Normal	Date:		
	wests _ ldeans _ Email _		71-	Project #	DILT. 41 (-12) 4175.(/by	Rush	Press	urization (Gas:
	City	State	ZIP	Project Name	Dolay Vic Plant	specify		N ₂ He	E -
mone	1144		Date	Time			ter Pres	ssure/Vac	
Lab I.D.	Field Sample I.D. (Location)	Can #	of Collection		Analyses Requested	Initial	Final	Receipt	Final (psi)
	JC+407 551112808	344 %(.	11-25-67	0575	TO 15	34	9		
	7 / 1 to 35 211 1808	35991		4645	Y, III	34	13		
	Joseph IAHINGA	91114		CD744	TO 15 16	30	8	13-1	
	70-10, IAX 112808	12675		2745	r.). Vi 16	29	8		
y Los	Tlen -								- 2
				4 - 4				Twick in	
								19.18	
F K									FAE
								And I	
Relinquish	ed by: (signature) Date/Time	Received b	y: (signature)	Date/Time	Notes:			1	
Relinquish	ed by: (signature) Date/Time	Received b	y: (signature)	Date/Time					
Relinquish	ed by: (signature) Date/Time	Received b	y: (signature)	Date/Time					
Lab	Shipper Name Air Bill	#	Temp (°C) C	Condition Custody Se	eals Intact?	Work	Order #	
Use Only					Yes No	None			
Offiny									